



P.K. 405,000  
Z=101,000  
Z=101,120  
S=1:100,000  
V=0,000



P.K. 410,000  
Z=101,000  
Z=101,140  
S=1:100,000  
V=0,000




P.K. 415,000  
Z=101,000  
Z=101,120  
S=1:100,000  
V=0,000




P.K. 420,000  
Z=101,000  
Z=101,140  
S=1:100,000  
V=0,000




P.K. 425,000  
Z=101,000  
Z=101,180  
S=1:100,000  
V=0,000




P.K. 430,000  
Z=101,000  
Z=101,220  
S=1:100,000  
V=0,000




P.K. 435,000  
Z=101,000  
Z=101,260  
S=1:100,000  
V=0,000




P.K. 440,000  
Z=101,000  
Z=101,300  
S=1:100,000  
V=0,000




P.K. 445,000  
Z=101,000  
Z=101,340  
S=1:100,000  
V=0,000




P.K. 450,000  
Z=101,000  
Z=101,380  
S=1:100,000  
V=0,000




P.K. 455,000  
Z=101,000  
Z=101,420  
S=1:100,000  
V=0,000




P.K. 460,000  
Z=101,000  
Z=101,460  
S=1:100,000  
V=0,000




P.K. 465,000  
Z=101,000  
Z=101,500  
S=1:100,000  
V=0,000




P.K. 470,000  
Z=101,000  
Z=101,540  
S=1:100,000  
V=0,000




P.K. 475,000  
Z=101,000  
Z=101,580  
S=1:100,000  
V=0,000




P.K. 480,000  
Z=101,000  
Z=101,620  
S=1:100,000  
V=0,000




P.K. 485,000  
Z=101,000  
Z=101,660  
S=1:100,000  
V=0,000




P.K. 490,000  
Z=101,000  
Z=101,700  
S=1:100,000  
V=0,000




P.K. 495,000  
Z=101,000  
Z=101,740  
S=1:100,000  
V=0,000




P.K. 500,000  
Z=101,000  
Z=101,780  
S=1:100,000  
V=0,000




P.K. 505,000  
Z=101,000  
Z=101,820  
S=1:100,000  
V=0,000




P.K. 510,000  
Z=101,000  
Z=101,860  
S=1:100,000  
V=0,000




P.K. 515,000  
Z=101,000  
Z=101,900  
S=1:100,000  
V=0,000




P.K. 520,000  
Z=101,000  
Z=101,940  
S=1:100,000  
V=0,000




P.K. 525,000  
Z=101,000  
Z=101,980  
S=1:100,000  
V=0,000




P.K. 530,000  
Z=101,000  
Z=102,020  
S=1:100,000  
V=0,000




P.K. 535,000  
Z=101,000  
Z=102,060  
S=1:100,000  
V=0,000




P.K. 540,000  
Z=101,000  
Z=102,100  
S=1:100,000  
V=0,000




P.K. 545,000  
Z=101,000  
Z=102,140  
S=1:100,000  
V=0,000




P.K. 550,000  
Z=101,000  
Z=102,180  
S=1:100,000  
V=0,000




P.K. 555,000  
Z=101,000  
Z=102,220  
S=1:100,000  
V=0,000




P.K. 560,000  
Z=101,000  
Z=102,260  
S=1:100,000  
V=0,000




P.K. 565,000  
Z=101,000  
Z=102,300  
S=1:100,000  
V=0,000



P.K. 570,000  
Z=101,000  
Z=102,340  
S=1:100,000  
V=0,000



P.K. 575,000  
Z=101,000  
Z=102,380  
S=1:100,000  
V=0,000



P.K. 580,000  
Z=101,000  
Z=102,420  
S=1:100,000  
V=0,000

